

The gas grill on the below appliances are designed to be used with the grill door fully open. It has come to our attention that IF THE GRILL DOOR IS CLOSED WITH THE GRILL BURNER LIT, DANGEROUS LEVELS OF CARBON MONOXIDE CAN BE PRODUCED.

N.B. The below products are perfectly safe to use if they are operated in accordance with the manufacturer's instructions.



Belling G755 White(50531081) & Belling Country Chef 100G
Anthracite(50531082) Anthracite(444445946) &
Belling GT755 White(444449050) Silver(444445945)

*Product code numbers in brackets

We are in the process of contacting customers who have bought one of the above products to arrange for an engineer to carry out a small modification to the grill door, which will prevent such toxic fumes being created should the grill door be closed, in error, when the grill burner is in use.

In the meantime:

DO NOT, UNDER ANY CIRCUMSTANCES, OPERATE THE GRILL UNLESS THE GRILL DOOR IS FULLY OPEN.

Safety Inspection

If you own any of the above Belling products with serial numbers beginning with 07 or 08, please email your contact details, product code number and serial number to safetynotice@belling.co.uk, so that we can arrange for one of our engineers to carry out a safety inspection and carry out any modifications required. Alternatively, please call one of our customer advisors on 0800 110 5729.

The serial number can be found on the data plate at the bottom front edge of the appliance.

